

Republic of the Philippines MUNICIPALITY OF PASUQUIN **llocos Norte**



REQUEST FOR QUOTATION

Date: 08.06.2025 2025 - 098 Qoutation NO. 2025.08.179

PR No:

Please qoute your lowest price on the item/s listed beow, subject to the General Conditions on the last page, stating the shortest time of delivery and submit your qoutation duly signed by your representative not later than AUGUST 12, 2025 @ 2:00PM in the return envelope attached herewith.

> PATRICK JOHN T. RATUITA, MAPA BACCHAIRMAN

- NOTE: 1. All entries must be type written
 - 2. Delivery period thirtyty (30) calendar days
 - 3. Warranty shall be for a period of six(6) months for supplies & materials, one(1) year for equipment, from date of acceptance by the procuring entity
 - 4. Price validity shall be for a period of one (1) month upon submission of the quotation
 - 5. The following documents shall be attached upon submission of the quotation:
 - a. Mayor's / Business Permit
 - b. Department of Trade and Industry
 - c. Certificate of Registration
 - d. PhilGEPS registration certificate/number
 - e. Income / Business Tax Return
 - f. Omnibus Sworn Statement (if applicable)

ITEM NO.	ITEM & DESCRIPTION	Brand/ Model	QTY.	UNIT	UNIT PRICE	TOTAL COST
1	Cover, Front Bumper	Wiodei	1	piece		
2	Cover, Fog Lamp, Left		1	piece	-	
3	Cover, Front bumper hole, Left		1	piece		
4	Nut		5	pieces		
5	Fender sub-assembly, front left		1	piece		
6	Bolt, with washer		5	pieces		
7	Hood Sub-assembly		1	piece		
8	Shield sub-assembly, fender splash, front left		1	piece		
9	Piece, rear bumper		5	pieces		
10	piece, Rear bumper		5	pieces		
11	Clip		10	pieces		
12	Screw, with washer tapping		5	pieces		
13	Grommet, Screw		5	pieces		
14	Clip, Pin Hold		10	pieces		
15	Retainer, Front fender liner		5	pieces		
16	Unit Assembly, headlamp, left		1	piece		
17	Cap sub-assembly, wheel		1	piece		
18	Support, front bumper side, left		1	piece		
19	Support, front bumper side, right		1	piece		
20	Labor Cost of External Panel Repair works	/			7	-
	Replace LH Front fender					
	Replace Front Bumper Cover		44,540,000			-
	Replace LH Front Door	Lorentz Alberta (Marie	Part of the last	-	Harrison W. Control	-
	Replace Hood Sub-Assembly		-	and the same of	M	
	Ereplace LH Headlamp Assembly (one side)					
21	Paint Labor (Accesing damages & sanding, Putty				The same party	
	shapping, Putty sanding & masking, Primer surface	er		***********	A CONTRACTOR OF THE PARTY OF TH	
	applicatio, primer surfacer sanding, masking,				The second second	
	Topcoating, Drying, Polishing)					
	Replace left front fender			1		
	Replace front bumper cover					
	Replace Left front door		1			
	Replace Hood sub-assembly		-			

22	Paint Materials (Putty, SandingPaper, Paints/Tints					
	Plastic Primer Surfacer< Solvent Gloves, Rags					
	Gloves, Rubbing Compound, High-Gloss					
	Compound, Paint Strainer/cups)					
	Replace Left front fender					
	Replace front bumper cover					
	Replace Left front door					
	Replace Hood Su-Assembly					
23	Internal Repair Works					
				total		
				Brand and Model	7	
			Delivery Period	;		
				Warranty	:	
er h	aving carefully read and accepted your General Conditions,	I/We qoute you o	n the item at pri	Price Validity ces noted above.	<u>.</u>	
	MGPIN - 2025.08.137			Printed Name/Signature		
	Repair and Maintenance of Municipal Vehicle (29058)		Timed Name/Signature			
				Tel. No./Cellphone No./Email Add.		

GENEVIEVE P. MAGAVILLA
'THOM I WALL HORTE